

SOUTH WARRANDYTE HALL

Place No. 201

ADDRESS 66 Hall Road
Warrandyte South

Last Update

DESCRIPTION -

Condition Good **Integrity** Intact
Threats **Key elements**
Designer

HISTORY

A simple, large, timber, single-storey, corrugated iron gable roofed hall. It has four-bay sides, a three-bay front and a skillion side extension. The hall is intact and in good condition.

The present hall is the third on that site, the first being accidentally burnt down, and the second destroyed in the 1939 bushfires [26]. These bushfires destroyed all the public buildings in South Warrandyte.

The Hall is thought to have been rebuilt after 1939 through local community efforts.

SOURCES

[1] Bruce Bence, 'The Mechanics' Institute Warrandyte 1882-1990', p.15

Creation Date Post 1939 **Change Dates**

Associations **Local Themes**

6.06 - Community halls

STATEMENT OF SIGNIFICANCE Of local significance as a community meeting place recreated through community efforts after the 1939 bushfires.

LEVEL

RECOMMENDATIONS

Heritage Register Listings

Register	Reference	Zoning	Status
-----------------	------------------	---------------	---------------

None Specified

Extent

Heritage Schedule

External Paint Controls: On VHR: VHR Ref No:

Internal Alteration Controls: Prohibited Uses:

Tree Controls: Aboriginal Heritage Place:

Outbuildings or Fences: Incorporated Plan: Incorporated Plan Details

Description:

Conservation Management

Extra Research

BIBLIOGRAPHY