

BUILDING IDENTIFICATION FORM 39

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS 83 BENDIGO ST (SE CORN. KIMBER ST.)

BUILDING TITLE _____ TYPE If not residence

EXISTING DESIGNATION HBR NER NTC

GRADING A B C D E F

STREETSCAPE 1 2 3 CONSERVATION AREA

SURVEY DATE 10.10.84 NEG. FILE 96-24

PERIOD 3.8.92 RP. 931-2
 Early Victorian Edwardian
 Victorian
 Late Victorian

CONSTRUCTION DATE c1870 (?) Source USNM

MATERIALS
 Walls WEATHERED Roof IRON

FORM
 Attached Detached

SIGNIFICANT FEATURES

early paint colour scheme <input type="checkbox"/>	eaves, roof or gable decoration <input type="checkbox"/>
original unpainted wall finish <input type="checkbox"/>	intact verandah decoration <input checked="" type="checkbox"/>
ornamental wall detailing <input type="checkbox"/>	early fence <input type="checkbox"/>
original doors/windows <input checked="" type="checkbox"/>	early garden <input checked="" type="checkbox"/> ?
intact verandah structure <input checked="" type="checkbox"/>	other prominent contrib. elevations <input type="checkbox"/>
original parapet <input type="checkbox"/>	<u>VER. END WALL</u> <input checked="" type="checkbox"/>
original roof form & finish <input checked="" type="checkbox"/>	<input type="checkbox"/>
original chimneys <input type="checkbox"/>	<input type="checkbox"/>



INTEGRITY RATING excellent good fair poor

ALTERATIONS & SPECIFIC GUIDELINES					
No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate
			<u>FENCE</u>	<u>S</u>	
			<u>CHIMNEY</u>	<u>S</u>	

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS
Unusual double gable corner building, with convex verandah roof.