

REPAINT TRIM IN TRADITIONAL COLOURS.

RESTORE UPPER LEVEL WINDOW GLAZING.



REPLACE FULLY GLAZED DOORS WITH ORIGINAL DOORS OR HALF GLAZED DOORS.

34 VIEW STREET

32

RECOMMENDATIONS:
RELOCATE/CONCEAL VENT PIPE.