

CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

LORRAINE HUDDLE 206513
LOUISE HONMAN
RICHARD AITKEN
1986

BUILDING ADDRESS **21 Candover st.**

Type **R** Original Use **R**

PRESENT BUILDING TITLE

EXISTING DESIGNATION & FILE No. HBR No. NER No. NTC FN. GRC No.

GRADING A B C D E S

STREETSCAPE LEVEL 1 2 3 CONSERVATION AREA

SURVEY DATE **21-3-86**

NEG. FILE **02-002**

PERIOD
Early Victorian
Victorian
Late Victorian
Edwardian
Inter War
Post War



MATERIALS
walls **tim.** roof **ci**

CONSTRUCTION DATE **1880** source

SIGNIFICANT FEATURES

original materials <input type="checkbox"/>	early paint colour scheme or original unpainted finish <input type="checkbox"/>	ornamental wall detailing <input type="checkbox"/>
original doors, windows, hoods <input checked="" type="checkbox"/>	intact verandah / porch structure <input type="checkbox"/>	original parapet <input type="checkbox"/>
original roof form and finish <input type="checkbox"/>	original chimneys <input type="checkbox"/>	eaves roof or gable decoration <input type="checkbox"/>
intact verandah decoration <input type="checkbox"/>	early fence <input type="checkbox"/>	early garden <input type="checkbox"/>
other prominent contributing elevations <input type="checkbox"/>		

INTEGRITY RATING excellent good fair poor

ALTERATIONS & SPECIFIC GUIDELINES						
No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
			Yard for S.G.			
			porch			
			removal of garden			

o : reinstate original design r : remove
s : reinstate sympathetic alternative ram: remove by approved method