

CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

LORRAINE HUDDLE 206592
LOUISE HONMAN
RICHARD AITKEN
1986

BUILDING ADDRESS **39 Candover st.**

Type **R** Original Use **R**

PRESENT BUILDING TITLE

EXISTING DESIGNATION & FILE No. HBR No. NER No. NTC FN. GRC No.

GRADING A B C D E S

STREETSCAPE LEVEL 1 2 3 CONSERVATION AREA

SURVEY DATE **24-2-86**

NEG. FILE **011-021 029**
011-021 030

PERIOD
Early Victorian
Victorian
Late Victorian
Edwardian
Inter War
Post War



MATERIALS
walls **tim** roof **ci**

CONSTRUCTION DATE **1880's** source

SIGNIFICANT FEATURES

original materials <input checked="" type="checkbox"/>	early paint colour scheme or original unpainted finish <input type="checkbox"/>	ornamental wall detailing <input type="checkbox"/>
original doors, windows, hoods <input checked="" type="checkbox"/>	intact verandah / porch structure <input checked="" type="checkbox"/>	original parapet <input type="checkbox"/>
original roof form and finish <input checked="" type="checkbox"/>	original chimneys <input type="checkbox"/>	eaves roof or gable decoration <input checked="" type="checkbox"/>
intact verandah decoration <input checked="" type="checkbox"/>	early fence <input checked="" type="checkbox"/>	early garden <input checked="" type="checkbox"/>
other prominent contributing elevations <input checked="" type="checkbox"/>	ledge <input checked="" type="checkbox"/>	<input type="checkbox"/>

INTEGRITY RATING excellent good fair poor

ALTERATIONS & SPECIFIC GUIDELINES						
No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.

o : reinstate original design r : remove
s : reinstate sympathetic alternative ram: remove by approved method

CITATION & HISTORY



Statement of Significance

REFERENCES

Sources of early photographs