

CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

LORRAINE HUDDLE 207031
LOUISE HONMAN
RICHARD AITKEN

1986

BUILDING ADDRESS *73 Clarence St*

Type *R* Original Use *R*

PRESENT BUILDING TITLE

EXISTING DESIGNATION & FILE No.

HBR No. NER No. NTC FN. GRC No.

GRADING A B C D E S

STREETSCAPE LEVEL 1 2 3 CONSERVATION AREA

SURVEY DATE *22.4.86*

NEG. FILE *035* *006*

PERIOD

Early Victorian
Victorian
Late Victorian
Edwardian
Inter War
Post War



MATERIALS

walls *wb* roof *cc*

CONSTRUCTION DATE source

SIGNIFICANT FEATURES

original materials	<input checked="" type="checkbox"/>	early paint colour scheme or original unpainted finish	<input type="checkbox"/>	ornamental wall detailing	<input type="checkbox"/>
original doors, windows, hoods	<input checked="" type="checkbox"/>	intact verandah / porch structure	<input checked="" type="checkbox"/>	original parapet	<input type="checkbox"/>
original roof form and finish	<input checked="" type="checkbox"/>	original chimneys	<input checked="" type="checkbox"/>	eaves-roof or gable decoration	<input checked="" type="checkbox"/>
intact verandah decoration	<input checked="" type="checkbox"/>	early fence	<input type="checkbox"/>	early garden	<input type="checkbox"/>
other prominent contributing elevations	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>

INTEGRITY RATING excellent good fair poor

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate
	<i>fence</i>	<i>R</i>	<i>for gate posts</i>	<i>R</i>	<i>conc. ver. structure S</i>

o : reinstate original design r : remove
s : reinstate sympathetic alternative ram: remove by approved method