

# CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

LORRAINE HUDDLE 201033  
 LOUISE HONMAN  
 RICHARD AITKEN

1986

BUILDING ADDRESS *77 Clarence St*

Type *R* Original Use *R*

PRESENT BUILDING TITLE

EXISTING DESIGNATION & FILE No. HBR No.  NER No.  NTC FN.  GRC No.

GRADING A  B  C  D  E  S

STREETSCAPE LEVEL 1  2  3  CONSERVATION AREA

SURVEY DATE *2.4.86*

NEG. FILE *035 004*

PERIOD  
 Early Victorian   
 Victorian   
 Late Victorian   
 Edwardian   
 Inter War   
 Post War



MATERIALS  
 walls *wb* roof *a*

CONSTRUCTION DATE source

SIGNIFICANT FEATURES

original materials	<input checked="" type="checkbox"/>	early paint colour scheme or original unpainted finish	<input type="checkbox"/>	ornamental wall detailing	<input type="checkbox"/>
original doors, windows, hoods	<input checked="" type="checkbox"/>	intact verandah / porch structure	<input checked="" type="checkbox"/>	original parapet	<input type="checkbox"/>
original roof form and finish	<input checked="" type="checkbox"/>	original chimneys	<input checked="" type="checkbox"/>	eaves, roof or gable decoration	<input checked="" type="checkbox"/>
intact verandah decoration	<input checked="" type="checkbox"/>	early fence	<input type="checkbox"/>	early garden	<input type="checkbox"/>
other prominent contributing elevations	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>

INTEGRITY RATING excellent  good  fair  poor

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate
					<i>fence</i>
					<i>cont. ver. fl.</i>
					<i>S</i>
					<i>S</i>

o : reinstate original design      r : remove  
 s : reinstate sympathetic alternative      farn: remove by approved method