

CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

LORRAINE HUDDLE 201050
 LOUISE HONMAN
 RICHARD AITKEN 1986

BUILDING ADDRESS 93 Clarence St Type R Original Use R

PRESENT BUILDING TITLE

EXISTING DESIGNATION & FILE No. HBR No. NER No. NTC FN. GRC No.

GRADING A B C D E S

STREETSCAPE LEVEL 1 2 3 CONSERVATION AREA

SURVEY DATE 29.11.86

NEG. FILE 034 032 - 036

PERIOD

Early Victorian

Victorian

Late Victorian

Edwardian

Inter War

Post War



MATERIALS

walls 10b roof ce

CONSTRUCTION DATE source extra nice new fence

SIGNIFICANT FEATURES

original materials	<input checked="" type="checkbox"/>	early paint colour scheme or original unpainted finish	<input type="checkbox"/>	ornamental wall detailing	<input type="checkbox"/>
original doors, windows, hoods	<input checked="" type="checkbox"/>	intact verandah / porch structure	<input type="checkbox"/>	original parapet	<input type="checkbox"/>
original roof form and finish	<input checked="" type="checkbox"/>	original chimneys	<input type="checkbox"/>	eaves roof or gable decoration	<input type="checkbox"/>
intact verandah decoration	<input type="checkbox"/>	early fence	<input type="checkbox"/>	early garden	<input type="checkbox"/>
other prominent contributing elevations	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>

INTEGRITY RATING excellent good fair poor

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate
	<u>fence</u>	<u>-</u>			<u>whole of ver. structure S</u>

o : reinstate original design r : remove
 s : reinstate sympathetic alternative ram : remove by approved method

CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

page 2

CITATION & HISTORY



Statement of Significance

REFERENCES

Sources of early photographs