

CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

LORRAINE HUDDLE 208094
LOUISE HONMAN
RICHARD AITKEN

1986

BUILDING ADDRESS *77 Gertrude St* Type *R* Original Use *R*

PRESENT BUILDING TITLE

EXISTING DESIGNATION & FILE No. HBR No. NER No. NTC FN. GRC No.

GRADING A B C D E S

STREETSCAPE LEVEL 1 2 3 CONSERVATION AREA

SURVEY DATE *28/6*

NEG. FILE *097 - 029*

PERIOD
 Early Victorian
 Victorian
 Late Victorian
 Edwardian
 Inter War
 Post War



MATERIALS
 walls *wb* roof *ci*

CONSTRUCTION DATE source *Research*

SIGNIFICANT FEATURES

original materials	<input checked="" type="checkbox"/>	early paint colour scheme or original unpainted finish	<input type="checkbox"/>	ornamental wall detailing	<input type="checkbox"/>
original doors, windows, hoods	<input checked="" type="checkbox"/>	intact verandah / porch structure	<input type="checkbox"/>	original parapet	<input type="checkbox"/>
original roof form and finish	<input checked="" type="checkbox"/>	original chimneys	<input type="checkbox"/>	<i>broken tiles</i>	<input checked="" type="checkbox"/>
intact verandah decoration	<input type="checkbox"/>	early fence	<input type="checkbox"/>	eaves roof or gable decoration	<input type="checkbox"/>
other prominent contributing elevations	<input type="checkbox"/>		<input type="checkbox"/>	early garden	<input type="checkbox"/>

INTEGRITY RATING excellent good fair poor

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate
	<i>fence</i>	-	<i>shutter</i>		
			<i>pergola</i>		
			<i>front door</i>		

o : reinstate original design r : remove
 s : reinstate sympathetic alternative ram : remove by approved method