

Appendix 2.3: Contemporary Photographs



Photo 3.01: Single storey interwar Bungalow styled dwelling, 2 Brawn Avenue.



Photo 3.02: Single storey interwar Bungalow style dwelling, 12 Brawn Avenue.



Photo 3.03: Atypical two storey interwar styled dwelling, 324 Wendouree Parade.



Photo 3.04: Interwar Bungalow styled dwelling, 1103 Gregory Street.



Photo 3.05: Interwar Old English styled dwelling, 1117 Gregory Street.



Photo 3.06: Postwar Bungalow Waterfall styled dwelling, 326 Wendouree Parade.



Photo 3.07: Concrete kerb and channel, Brawn Avenue.



Photo 3.08: Concrete driveway cross over, Brawn Avenue.



Photo 3.09: Early brick pier and plinth fence with geometric trussed steel bays to interwar Bungalow dwelling, 1108 Gregory Street.



Photo 3.10: Early brick pier and plinth fence with geometric trussed steel bays to interwar dwelling, 1125 Gregory Street.



Photo 3.11: Early solid brick front fence to Bungalow styled dwelling, 22 Brawn Avenue.



Photo 3.12: Early solid brick front fence to Bungalow styled dwelling, 3 Haddon Street.



Photo 3.13: Mature Oak trees behind dwelling at 302 Wendouree Parade.



Photo 3.14: Mature Liquid Amber tree in the front garden at 304 Wendouree Parade.