BUILDING IDENTIFICATION FORM 1/6 RICHMOND CONSERVATION STUDY
BUILDING ADDRESS 6 BAKER ST
BUILDING TITLE HAZELDENE TYPE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 29.4.04 NEG. FILE 131.72 PERIOD 15.3.92 PV. 935-6-9 Early Victorian Edwardian Victorian Late Victorian Edwardian Victorian Edwardian MATERIALS Walls 15.4 MATERIALS Walls 15.4 MATERIALS SIGNIFICANT FEATURES early paint colour scheme colour scheme conginal unpainted wall finish ornamental wall detailing ornamental wall detailing intact verandah structure conginal parapet original parapet conginal parapet conginal conginal conginal conginal chimneys
INTEGRITY RATING excellent good fair poor
ALTERATIONS & SPECIFIC GUIDELINES No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G.
No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G.
SECURITY DOOR.
O = reinstate original designs
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method COMMENTS BI-chrane back villa of excellent integrity, with unpainted back walls, chimneys wanted iran fence and gate is a time guniver of early fence grules.

. .

1 .