

BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS *5 BARKLY AVE*

BUILDING TITLE

TYPE

If not residence

EXISTING DESIGNATION

HBR ☐

NER ☐

NTC ☐

GRADING

A ☐

B ☐

C ☐

D ☒

E ☐

F ☐

STREETSCAPE

1 ☐

2 ☐

3 ☒

CONSERVATION AREA ☒

SURVEY DATE *15.8.84*

NEG. FILE *73-18*

PERIOD

Early Victorian ☐

Edwardian ☐

Victorian ☐

Late Victorian ☒

CONSTRUCTION DATE

Source

MATERIALS

Walls

BRICK

Roof

IRON

FORM

Attached ☒

Detached ☐

SIGNIFICANT FEATURES

early paint
colour scheme ☐

eaves, roof or
gable decoration ☒

original unpainted
wall finish ☐

intact verandah
decoration ☐

ornamental
wall detailing ☐

early
fence ☒

original
doors/windows ☒

early
garden ☐

intact verandah
structure ☒

other prominent
contrib. elevations ☐

original
parapet *side* ☒

original roof
form & finish ☒

original
chimneys ☒



INTEGRITY RATING

excellent ☐

good ☐

fair ☒

poor ☐

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
					<i>PAINTED BRICKWORK</i>	<i>RAM</i>

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS