BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY
BUILDING ADDRESS 1 BARKLY AVE
BUILDING TITLE TYPE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 16.8.84 NEG. FILE 13-17 PERIOD Early Victorian Edwardian Date Source CONSTRUCTION DATE Source
MATERIALS Walls IMPER ASHLAR Roof IRON FORM Attached Detached SIGNIFICANT FEATURES early paint colour scheme gable decoration intact verandah decoration wall finish decoration original wall detailing early garden garden structure coriginal parapet original parapet original confirm finish original chimneys coriginal chimneys coriginal chimneys
INTEGRITY RATING excellent good fair poor
ALTERATIONS & SPECIFIC GUIDELINES No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G. POOR 9 VERANDAM POST S
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method COMMENTS