BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY
BUILDING ADDRESS IS BARKLY AVE
BUILDING TITLE CART HEW TYPE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREET\$CAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 19.8.84 NEG. FILE 13-13
PERIOD Early Victorian Edwardian Victorian Late Victorian
CONSTRUCTION DATE Source
MATERIALS Walls TIMBER ASKUAR Roof IRON
FORM Attached Detached Detached
SIGNIFICANT FEATURES early paint colour scheme gable decoration gable gable decoration gable decoration gable decoration gable decoration gable decoration gable decoration gable gab
INTEGRITY RATING excellent good fair poor ALTERATIONS & SPECIFIC GUIDELINES
No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G.
FENCE
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method
COMMENTS