

BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS

43 BENDIGO ST

BUILDING TITLE

TYPE

If not residence

SHOP/HOUSE

EXISTING DESIGNATION

HBR

☐

NER

☐

NTC

☐

GRADING

A

☐

B

☐

C

☐

D

☒

E

☐

F

☐

STREETSCAPE

1

☐

2

☐

3

☐

CONSERVATION AREA

☐

SURVEY DATE 10.10.84

NEG. FILE 96-33

PERIOD

Early Victorian

☐

Edwardian

☐

Victorian

☐☐

Late Victorian

☒

CONSTRUCTION DATE

Source

MATERIALS

Walls RENDER

Roof IRON

FORM

Attached

☐

Detached

☒

SIGNIFICANT FEATURES

early paint
colour scheme

☐

eaves, roof or
gable decoration

☐

original unpainted
wall finish

☐

intact verandah
decoration

☐

ornamental
wall detailing

☐

early
fence

☐

original
doors/windows

☒

early
garden

☐

intact verandah
structure

☐

other prominent
contrib. elevations

☐

original
parapet

☒☐

original roof
form & finish

☒☐

original
chimneys

☒☐

INTEGRITY RATING

excellent

☐

good

☒

fair

☐

poor

☐

ALTERATIONS & SPECIFIC GUIDELINES

No.

Sympathetic

S.G.

Inappropriate

S.G.

Extremely Inappropriate

S.G.

					WINDOW INFILLS	R

O = reinstate original designs

S = reinstate sympathetic alternative

R = remove

RAM = Remove by approved method

COMMENTS