BUILDING IDENTIFICATION FORM
RICHMOND CONSERVATION STUDY
BUILDING ADDRESS 71 BENDICO ST
BUILDING TITLE TYPE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 10.10.84 NEG. FILE 96-28
PERIOD
Early Victorian Edwardian
Victorian
Late Victorian
CONSTRUCTION DATE Source
MATERIALS W.H. (121 - 122 - 12
Walls WENTHERB D. Roof IRON
FORM Attached Detached Detached
SIGNIFICANT FEATURES
early paint eaves, roof or gable decoration
original unpainted intact verandah wall finish decoration
ornamental early wall detailing fence
original early deors/ windows garden
intact verandah other prominent structure contrib. elevations
original
parapet original roof
form & finish original
chimneys
INTEGRITY RATING excellent good fair poor
ALTERATIONS & SPECIFIC GUIDELINES
No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G.
VERMONH FEINCE .
SULV HOOD.
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method
COMMENTS