

BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS 88-94 BENDIGO ST

BUILDING TITLE _____ TYPE If not residence

EXISTING DESIGNATION HBR NER NTC

GRADING A B C D E F

STREETSCAPE 1 2 3 CONSERVATION AREA

SURVEY DATE 25.6.84 NEG. FILE 7-4

PERIOD
 Early Victorian Edwardian
 Victorian
 Late Victorian


CONSTRUCTION DATE _____ Source _____

MATERIALS
 Walls CEMENT RENDER (90,92) BRICK (88,94) Roof IRON

FORM
 Attached Detached

SIGNIFICANT FEATURES

early paint colour scheme <input type="checkbox"/>	eaves, roof or gable decoration <u>88,94</u> <input checked="" type="checkbox"/>
original unpainted wall finish <u>88</u> <input checked="" type="checkbox"/>	intact verandah decoration <u>88</u> <input checked="" type="checkbox"/>
ornamental wall detailing <input type="checkbox"/>	early fence <input type="checkbox"/>
original doors/windows <input type="checkbox"/>	early garden <input type="checkbox"/>
intact verandah structure <u>88</u> <input checked="" type="checkbox"/>	other prominent contrib. elevations <input type="checkbox"/>
original parapet <input type="checkbox"/>	
original roof form & finish <input checked="" type="checkbox"/>	
original chimneys <u>88,94</u> <input checked="" type="checkbox"/>	



INTEGRITY RATING excellent good fair poor

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
			FENCES	S		
90,92					WINDOWS	O

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS