BUILDING IDENTIFICATION FORM
BUILDING ADDRESS 20,22 BENT ST.
BUILDING TITLE TYPE If not residence
GRADING A B C D F F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 3.8.84 NEG. FILE 65-1 PERIOD
Early Victorian Edwardian Victorian
Late Victorian
CONSTRUCTION DATE Source
Walls BRICK Roof IRON
FORM Attached Detached Detached
SIGNIFICANT FEATURES         early paint colour scheme       gable decoration gable decoration decoration decoration decoration decoration decoration decoration decoration decoration decoration decoration decoration decoration decoration decoration garden         original doors/windows       early fance early garden         original doors/windows       early garden         original parapet       other prominent contrib, elevations         original parapet       other prominent contrib, elevations         original chimneys       excellent       good       fair       poor
ALTERATIONS & SPECIFIC GUIDELINES
No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G.
FENCES 3
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method
COMMENTS