

BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS *164, 166 BRIGHTON ST.*

BUILDING TITLE *KOREIN (166) MAROLIRA (164)* TYPE If not residence

EXISTING DESIGNATION HBR NER NTC

GRADING A B C D E F

STREETSCAPE 1 2 3 CONSERVATION AREA

SURVEY DATE *22.8.84* NEG. FILE *71 - 7*

PERIOD
 Early Victorian Edwardian
 Victorian
 Late Victorian

CONSTRUCTION DATE Source

MATERIALS
 Walls *BRICK* Roof *IRON*

FORM
 Attached *SEMI* Detached

SIGNIFICANT FEATURES

early paint colour scheme <input type="checkbox"/>	eaves, roof or gable decoration <input checked="" type="checkbox"/>
original unpainted wall finish <input type="checkbox"/>	intact verandah decoration <input checked="" type="checkbox"/>
ornamental wall detailing <input type="checkbox"/>	early fence <input checked="" type="checkbox"/>
original doors/windows <input checked="" type="checkbox"/>	early garden <input type="checkbox"/>
intact verandah structure <input checked="" type="checkbox"/>	other prominent contrib. elevations <input checked="" type="checkbox"/> <i>164</i>
original parapet <input type="checkbox"/>	<i>VER. & PATH TILES?</i> <input checked="" type="checkbox"/>
original roof form & finish <i>166</i> <input checked="" type="checkbox"/>	<input type="checkbox"/>
original chimneys <input checked="" type="checkbox"/>	<input type="checkbox"/>



INTEGRITY RATING excellent good *166* fair *164* poor

ALTERATIONS & SPECIFIC GUIDELINES						
No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
<i>164</i>					<i>METAL ROOF TILES</i>	<i>O</i>
<i>166</i>			<i>MISSING DOOR GLASS</i>	<i>O</i>		

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS