

BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS **292 BURNLEY ST.**

BUILDING TITLE **ST. BARTHOLOMEWS**

TYPE **CHURCH, CHURCH HALL**
If not residence **& PRESBYTERY**

EXISTING DESIGNATION HBR NER NTC

GRADING A B C D E F

STREETSCAPE 1 2 3 CONSERVATION AREA

SURVEY DATE **30.6.84** NEG. FILE **1A-22**

PERIOD

Early Victorian Edwardian
Victorian **Inter War**
Late Victorian

CONSTRUCTION DATE **1926** (earlier stone 1910) Source **FOUNDATION STONE**

MATERIALS


Walls **BRICK** Roof **CEMENT TILE**
IRON (PRES.)

FORM

Attached Detached

SIGNIFICANT FEATURES

early paint colour scheme	<input checked="" type="checkbox"/>	eaves, roof or gable decoration	<input checked="" type="checkbox"/>
original unpainted wall finish	<input checked="" type="checkbox"/>	intact verandah decoration	<input type="checkbox"/>
ornamental wall detailing	<input checked="" type="checkbox"/>	early fence	<input type="checkbox"/>
original doors/windows	<input checked="" type="checkbox"/>	early garden	<input type="checkbox"/>
intact verandah structure	<input type="checkbox"/>	other prominent contrib. elevations	<input checked="" type="checkbox"/>
original parapet	<input checked="" type="checkbox"/>		<input type="checkbox"/>
original roof form & finish	<input checked="" type="checkbox"/>		<input type="checkbox"/>
original chimneys	<input type="checkbox"/>		<input type="checkbox"/>



INTEGRITY RATING excellent good fair poor

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS

Early modern style brick church, constructed in 1926, featuring fine brick detailing to articulate the building massing.