BUILDING ADDRESS 300 Church Street BUILDING TITLE Formor Westleyan Chape! TYPE In not residence In not	BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY
EXISTING DESIGNATION HBR NER R/01/08 NTC FN. 2891 GRADING A B C D D E F F STREETSCAPE 1 2 3 CONSERVATION AREA SURVEY DATE 26.7.84 NEG, FILE 28-26 PERIOD Early Victorian Construction DATE MATERIALS Walls Bluestone & Render Roof I ron Tilles FORM Attached Detached Sides decoration plant decoration and form of finish constructions are constructed and	BUILDING ADDRESS 300 Church Street
EXISTING DESIGNATION HBR NER R/01/08 MTC FN.2891 GRADING A B C D D E F F STREETSCAPE 1 2 3 CONSERVATION AREA SURVEY DATE 26.7.84 NEG. FILE 28-26 PERIOD Early Victorian Detached Victorian Late Victorian Detached MATERIALS SIGNIFICANT FEATURES safe point solic decertion victorian Detached SIGNIFICANT FEATURES safe point solic decertion victorian Si des C C D D E F F CONSERVATION AREA SURVEY DATE 26.7.84 NEG. FILE 28-26 PERIOD Edwardian Detached SIGNIFICANT FEATURES safe point solic decertion victorian Detached Detached SIGNIFICANT FEATURES safe point solic decertion victorian Detached Detache	Latin and a series of the Medicine Observation
STREETSCAPE 1 2 3 CONSERVATION AREA SURVEY DATE 26.7.84 NEG. FILE 28-26 PERIOD Early Victorian	
SURVEY DATE 26.7.84 NEG. FILE 28-26 PERIOD Early Victorian	GRADING A B C D E F
PERIOD Early Victorian Late Victorian CONSTRUCTION DATE MATERIALS Walls B1 uestone & Render Roof Iron Titles FORM Attached Detached SIGNIFICANT FEATURES and y paint color shore grade decoration of grade gra	STREETSCAPE 1 2 3 CONSERVATION AREA
Early Victorian	SURVEY DATE 26.7.84 NEG. FILE 28-26
ALTERATIONS & SPECIFIC GUIDELINES No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G. Painted Render RAM O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method COMMENTS Iron tile roof restored 1972. These tiles were introduced in the 1840's	Early Victorian
No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G. Painted Render RAM O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method COMMENTS Iron tile roof restored 1972. These tiles were introduced in the 1840's	INTEGRITY RATING excellent good fair poor
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method COMMENTS Iron tile roof restored 1972. These tiles were introduced in the 1840's	
COMMENTS Iron tile roof restored 1972. These tiles were introduced in the 1840's	
COMMENTS Iron tile roof restored 1972. These tiles were introduced in the 1840's	
COMMENTS Iron tile roof restored 1972. These tiles were introduced in the 1840's	
COMMENTS Iron tile roof restored 1972. These tiles were introduced in the 1840's	
COMMENTS Iron tile roof restored 1972. These tiles were introduced in the 1840's	
	COMMENTS Iron tile roof restored 1972. These tiles were introduced in the 1840's