| BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY | | | | | |
|--|-------------------------------------|--------------------------|-----------------------|----------------------------|---|
| BUILDING ADDRESS 37 | CLIFTON ST | | | | *************************************** |
| BUILDING TITLE | | I | TYPE If not residence | | |
| EXISTING DESIGNATION | HBR 🗀 | NER _ | □ NTC | | |
| GRADING A | В С | D | E | F | |
| STREETSCAPE 1 | | CONSERVATION AREA | | | |
| SURVEY DATE 30.7.84 | NEG. FILE 36-3 | | | | |
| PERIOD | | | | | |
| Early Victorian | Edwardian | | | | |
| Victorian | | | | | |
| Late Victorian | | | | h. | |
| CONSTRUCTION DATE | Source | | | | |
| MATERIALS | 10.01 | | | | # |
| | Roof IRON | , real | 1 | | |
| FORM Attached D | Detached | 100000 | | B 200 | |
| SIGNIFICANT FEATURES | | | WATERWASE WASE | 1 | |
| early paint | eaves, roof or | Annual Processing Street | | | |
| colour scheme | intact verandah | . / | | | |
| wall finish ornamental | decoration | | - 2 | 1 | 144 |
| wall detailing | fence early | | | | As a |
| original doors/windows | garden | | | | |
| intact verandah structure | other prominent contrib. elevations | | | | |
| original parapet | | | | | |
| original roof form & finish | | - | | | |
| original chimneys | | | | | |
| | | | | SECTION OF SECTION SECTION | |
| INTEGRITY RATING | excellent goo | od 🔲 | fair | poor | |
| ALTERATIONS & SPECIFIC | | | | | |
| No. Sympathetic | S.G. Inappro | priate | S.G. Extremely I | nappropriate | S.G. |
| | | | FENCE | | 5 |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| O = reinstate original designs | S = reinstate sympathetic alterna | tive R = remo | ve RAM = Remove b | v approved meth | od Od |
| COMMENTS | o Temstate sympathetic atterna | icive II - TellIO | A LITANI - ITEHIOVE D | y approved meth | ou . |
| | | | | | |