

BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS *CREMORNE ST.*

BUILDING TITLE *STATE SCHOOL No. 2084*

TYPE
If not residence

EXISTING DESIGNATION HBR ☒ NER ☐ NTC ☐

GRADING A ☐ B ☐ C ☒ D ☐ E ☐ F ☐

STREETSCAPE 1 ☐ 2 ☐ 3 ☐ CONSERVATION AREA ☐

SURVEY DATE NEG. FILE *120-15*

PERIOD

Early Victorian ☐ Edwardian ☐
Victorian ☐
Late Victorian ☒

CONSTRUCTION DATE Source

MATERIALS

Walls *Brick* Roof *Slate*

FORM

Attached ☐ Detached ☒

SIGNIFICANT FEATURES

early paint colour scheme <input type="checkbox"/>	eaves, roof or gable decoration <input checked="" type="checkbox"/>
original unpainted wall finish <input checked="" type="checkbox"/>	intact verandah decoration <input checked="" type="checkbox"/>
ornamental wall detailing <input checked="" type="checkbox"/>	early fence <input type="checkbox"/>
original doors/windows <input checked="" type="checkbox"/>	early garden <input type="checkbox"/>
intact verandah structure <input checked="" type="checkbox"/>	other prominent contrib. elevations <input checked="" type="checkbox"/>
original parapet <input type="checkbox"/>	
original roof form & finish <input checked="" type="checkbox"/> <i>CREMORNE ST.</i>	
original chimneys <input checked="" type="checkbox"/>	



INTEGRITY RATING excellent ☒ good ☒ fair ☐ poor ☐
CREMORNE ST. *DOVER ST.*

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
<i>DOVER ST.</i>			<i>CEMENT ROOF TILES O</i>			
<i>DOVER ST.</i>			<i>FENCE</i>	<i>S</i>		
<i>CREMORNE ST.</i>			<i>FENCE</i>	<i>S</i>		

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS *TWO GOOD EXAMPLES OF 19TH CENTURY EDUCATION DEPARTMENT ARCHITECTURE. THE CREMORNE ST. BUILDING BUILT IN 1877, DOVER ST. BUILDING IN 1890.*

CREMORNE ST.