## **BUILDING IDENTIFICATION FORM** RICHMOND CONSERVATION STUDY CUBITT **BUILDING ADDRESS** 157, 159 TYPE **BUILDING TITLE** If not residence **HBR** NER NTC **EXISTING DESIGNATION** $\mathsf{D} \square$ E [ В GRADING 1 2 3 [ **CONSERVATION AREA** STREETSCAPE NEG. FILE 62 SURVEY DATE 3.8.84 **PERIOD** Edwardian Early Victorian Victorian Late Victorian **CONSTRUCTION DATE** Source MATERIALS Walls BRICK Roof 1ROW **FORM** 55m/ Detached Attached SIGNIFICANT FEATURES eaves, roof or early paint gable decoration colour scheme intact verandah original unpainted wall finish decoration early fence ornamental wall detailing original doors/windows 157 garden intact verandah other prominent contrib. elevations structure original parapet original roof form & finish original INTEGRITY RATING fair poor excellent good **ALTERATIONS & SPECIFIC GUIDELINES** Sympathetic S.G. S.G. Extremely Inappropriate S.G. No. Inappropriate PAINTED BRICK RAN DOOR 5 O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method COMMENTS