

# BUILDING IDENTIFICATION FORM

## RICHMOND CONSERVATION STUDY

**BUILDING ADDRESS** The Vaucluse

**BUILDING TITLE** F.C.J. Convent

**TYPE**

If not residence ☐ Convent ☒

**EXISTING DESIGNATION** HBR ☐ **NER** ☐ **NTC** ☐ FN. 3507

**GRADING** A ☐ B ☒ C ☐ D ☐ E ☐ F ☐

**STREETSCAPE** 1 ☒ 2 ☐ 3 ☐

**CONSERVATION AREA** ☒

**SURVEY DATE** 1.12.84 **NEG. FILE** 105-14, 15

**PERIOD**

Early Victorian ☐ Edwardian ☒  
Victorian ☐  
Late Victorian ☐

**CONSTRUCTION DATE** **Source**

**MATERIALS**


Walls Brick ☒ Roof Slate ☒

**FORM**

Attached ☐ Detached ☒

**SIGNIFICANT FEATURES**

early paint colour scheme <input type="checkbox"/>	eaves, roof or gable decoration <input checked="" type="checkbox"/>
original unpainted wall finish <input checked="" type="checkbox"/>	intact verandah decoration <input checked="" type="checkbox"/>
ornamental wall detailing <input checked="" type="checkbox"/>	early fence <input type="checkbox"/>
original doors/windows <input checked="" type="checkbox"/>	early garden <input type="checkbox"/>
intact verandah structure <input checked="" type="checkbox"/>	other prominent contrib. elevations <input type="checkbox"/>
original parapet <input type="checkbox"/>	Grotto <input checked="" type="checkbox"/>
original roof form & finish <input checked="" type="checkbox"/>	<input type="checkbox"/>
original chimneys <input checked="" type="checkbox"/>	<input type="checkbox"/>



**INTEGRITY RATING** excellent ☒ good ☐ fair ☐ poor ☐

**ALTERATIONS & SPECIFIC GUIDELINES**

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
					Fence on Vaucluse	S

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

**COMMENTS**