

BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS The Vaucluse

BUILDING TITLE F.C.J. Chapel

TYPE

If not residence

EXISTING DESIGNATION HBR ☐ NER ☐ NTC ☐ FN. 3507

GRADING A ☐ B ☒ C ☐ D ☐ E ☐ F ☐

STREETSCAPE 1 ☒ 2 ☐ 3 ☐ CONSERVATION AREA ☒

SURVEY DATE NEG. FILE 105-16

PERIOD

Early Victorian ☐ Edwardian ☐
Victorian ☐
Late Victorian ☒

CONSTRUCTION DATE Source

MATERIALS


Walls Brick Roof Slate

FORM

Attached ☐ Detached ☐

SIGNIFICANT FEATURES

early paint colour scheme <input type="checkbox"/>	eaves, roof or gable decoration <input type="checkbox"/>
original unpainted wall finish <input checked="" type="checkbox"/>	intact verandah decoration <input type="checkbox"/>
ornamental wall detailing <input checked="" type="checkbox"/>	early fence <input type="checkbox"/>
original doors/windows <input checked="" type="checkbox"/>	early garden <input type="checkbox"/>
intact verandah structure <input type="checkbox"/>	other prominent contrib. elevations <input type="checkbox"/>
original parapet <input type="checkbox"/>	
original roof form & finish <input checked="" type="checkbox"/>	
original chimneys <input type="checkbox"/>	



INTEGRITY RATING excellent ☒ good ☐ fair ☐ poor ☐

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
					Fence on Vaucluse	S

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS