BUILDING IDENTIFICATION FORM
BUILDING ADDRESS 57 POCKER ST
BUILDING TITLE TYPE
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 30.7.84 NEG. FILE 35-26
PERIOD Early Victorian Early Victorian Edwardian Victorian Image: Comparison of the second secon
CONSTRUCTION DATE Source
MATERIALS Walls CEMENT RENDER Roof IRON
FORM Attached Detached SIGNIFICANT FEATURES early paint colour scheme eaves, roof or gable decoration original unpainted wall finish intact verandah decoration ornamental wall detailing early fence
original doors/windows early garden intact verandah structure other prominent contrib. elevations original parapet intact verandah original coriginal chimneys intact verandah
INTEGRITY RATING excellent good fair poor
ALTERATIONS & SPECIFIC GUIDELINES No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G. No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G. No. PAINTED RENDER RAM FENICE S
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method COMMENTS
Well announced Victorian dwelling featuring cast ivan decoration and prominent chimneys and chimney pots.