| BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY | |
|---|---|
| BUILDING ADDRESS 5 GEORGE ST | |
| BUILDING TITLE | TYPE If not residence |
| EXISTING DESIGNATION HBR | NER NTC |
| GRADING A B C | D E F F |
| STREETSCAPE 1 2 3 | CONSERVATION AREA |
| SURVEY DATE 5.7.84 NEG. FILE 34-31 | |
| PERIOD Early Victorian Edwardian Victorian Late Victorian | |
| CONSTRUCTION DATE Source | → |
| MATERIALS ROUGH CAST Walls Roof SLATE | |
| FORM Attached Detached | |
| SIGNIFICANT FEATURES | |
| early paint eaves, roof or gable decoration | |
| original unpainted intact verandah wall finish decoration | |
| ornamental early wall detailing fence | |
| original early ? doors/windows garden | |
| intact verandah other prominent structure contrib. elevations | |
| original parapet | make places and the second of |
| original roof form & finish | |
| original chimneys | |
| | |
| INTEGRITY RATING excellent good | d fair poor |
| ALTERATIONS & SPECIFIC GUIDELINES | |
| No. Sympathetic S.G. Inapprop | |
| | VERANDAH INFILL R |
| | VERANDAH INFILL R GARAGE R |
| | CALLAGO. |
| | |
| | |
| O = reinstate original designs S = reinstate sympathetic alternat | ive R = remove RAM = Remove by approved method |
| COMMENTS | |