

# BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS **8-10 GEORGE ST**

BUILDING TITLE **'GLENISLA' & 'GLENLUCE'**

TYPE  
If not residence

EXISTING DESIGNATION HBR  NER  NTC

GRADING A  B  C  D  E  F

STREETSCAPE 1  2  3  CONSERVATION AREA

SURVEY DATE **5.7.04** NEG. FILE **34-28**

PERIOD  
Early Victorian  Edwardian   
Victorian   
Late Victorian

CONSTRUCTION DATE Source

MATERIALS  
Walls **BRICK** Roof **IRON**

FORM  
Attached  **SEMI** Detached

SIGNIFICANT FEATURES

early paint colour scheme	<input type="checkbox"/>	eaves, roof or gable decoration	<input type="checkbox"/>
original unpainted wall finish	<input checked="" type="checkbox"/>	intact verandah decoration	<input checked="" type="checkbox"/>
ornamental wall detailing	<input type="checkbox"/>	early fence	<b>8</b> <input checked="" type="checkbox"/>
original doors/windows	<input checked="" type="checkbox"/>	early garden	<input type="checkbox"/>
intact verandah structure	<input checked="" type="checkbox"/>	other prominent contrib. elevations	<input type="checkbox"/>
original parapet	<input checked="" type="checkbox"/>	<b>HEDGE 8</b>	<input checked="" type="checkbox"/>
original roof form & finish	<input checked="" type="checkbox"/>	<b>TILED VERANDAH FLOORS</b>	<input checked="" type="checkbox"/>
original chimneys	<input checked="" type="checkbox"/>		<input type="checkbox"/>



INTEGRITY RATING excellent  good  fair  poor

## ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
<b>10</b>			<b>FENCE</b>	<b>S</b>		

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS