

BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS 1 Gleadell Street

BUILDING TITLE

TYPE Former Gas
If not residence Inspector's residence

EXISTING DESIGNATION HBR ☐ NER ☐ NTC ☒ FN. 3996

GRADING A ☐ B ☒ C ☐ D ☐ E ☐ F ☐

STREETSCAPE 1 ☐ 2 ☐ 3 ☐ CONSERVATION AREA ☐

SURVEY DATE 25.7.84 NEG. FILE 99-22
51-29

PERIOD

Early Victorian ☐ Edwardian ☐
Victorian ☐
Late Victorian ☒

CONSTRUCTION DATE Source

MATERIALS


Walls Polychromatic Brickwork Roof Slate

FORM

Attached ☐ Detached ☒

SIGNIFICANT FEATURES

early paint colour scheme <input type="checkbox"/>	eaves, roof or gable decoration <input checked="" type="checkbox"/>
original unpainted wall finish <input checked="" type="checkbox"/>	intact verandah decoration <input type="checkbox"/>
ornamental wall detailing <input checked="" type="checkbox"/>	early fence <input type="checkbox"/>
original doors/windows <input checked="" type="checkbox"/>	early garden <input type="checkbox"/>
intact verandah structure <input type="checkbox"/>	other prominent contrib. elevations (sides) <input checked="" type="checkbox"/>
original parapet <input type="checkbox"/>	<input type="checkbox"/>
original roof form & finish <input checked="" type="checkbox"/>	<input type="checkbox"/>
original chimneys <input checked="" type="checkbox"/>	<input type="checkbox"/>



INTEGRITY RATING excellent ☒ good ☐ fair ☐ poor ☐

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
			Door Grille	R		
			Side Gate & Fence	R		
					Exposed Electrical Conduit	R

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS