

BUILDING IDENTIFICATION FORM 63

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS

6, 4 HUNTER ST.

BUILDING TITLE

TYPE

If not residence

EXISTING DESIGNATION

HBR

NER

NTC

GRADING

A

B

C

D

E

F

STREETSCAPE

1

2

3

CONSERVATION AREA

SURVEY DATE *4.10.84*

NEG. FILE *93-12*

PERIOD

3.B.92 RP.

931-32

Early Victorian

Edwardian

Victorian

Late Victorian

CONSTRUCTION DATE

Source

MATERIALS

Walls *BRICK*

Roof

IRON

FORM

Attached

SEMI

Detached

SIGNIFICANT FEATURES

early paint colour scheme

eaves, roof or gable decoration

original unpainted wall finish

intact verandah decoration

ornamental wall detailing

early fence

original doors/windows

early garden

intact verandah structure

other prominent contrib. elevations

original parapet

original roof form & finish

original chimneys

INTEGRITY RATING

excellent

good

fair

poor

ALTERATIONS & SPECIFIC GUIDELINES

No.

Sympathetic

S.G.

Inappropriate

S.G.

Extremely Inappropriate

S.G.

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
					<i>FENCES</i>	<i>S</i>

O = reinstate original designs

S = reinstate sympathetic alternative

R = remove

RAM = Remove by approved method

COMMENTS

brick

This simple brick banding.

brick structure is well defined by string coursing, and it retains a concave single storey verandah.

