BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY	
BUILDING ADDRESS 6,8,10,12 JA	
BUILDING TITLE	TYPE If not residence
EXISTING DESIGNATION HBR	NER NTC
GRADING A B C D E F	
STREETSCAPE 1 2 3	CONSERVATION AREA
SURVEY DATE 15.8.84 NEG. FILE 98-20  PERIOD  Early Victorian Edwardian Late Victorian Late Victorian	
CONSTRUCTION DATE Source	
MATERIALS Walls BRICK Roof IRON  FORM Attached Detached	
SIGNIFICANT FEATURES	
early paint colour scheme  original unpainted wall finish  ornamental wall detailing  original intact verandah decoration  early fence  early garden  intact verandah structure  original parapet  original parapet  original conditions  original parapet  original parapet  original chimneys	
INTEGRITY RATING excellent good fair poor	
ALTERATIONS & SPECIFIC GUIDELINES  No. Sympathetic S.G. Inapprop	
12 WINDOW	PAINTER BRICKWORK RAW
B FENCE	
O = reinstate original designs S = reinstate sympathetic alternate	tive R = remove RAM = Remove by approved method
comments This van of Victorian adtages are attractively situated to follow the topography of the area, and vetain a dequal of integrity with buillnose verandahs, and	