BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY	
BUILDING ADDRESS 119 KENT	57
BUILDING TITLE	TYPE If not residence
EXISTING DESIGNATION HBR	NER NTC
GRADING A B C D E F	
STREETSCAPE 1 2 3	CONSERVATION AREA
SURVEY DATE 11.9.84 NEG. FILE 29-33	
PERIOD  Early Victorian Edwardian	
Victorian Late Victorian	
CONSTRUCTION DATE Source	
MATERIALS	
Walls TIMBER ASHLAR ROOF IRON	
FORM	
Attached Detached  SIGNIFICANT FEATURES	MYADA NE
early paint eaves, roof or gable decoration  original unpainted intact verandah decoration	
ornamental early wall detailing fence	
original early doors/windows garden	
intact verandah other prominent structure contrib, elevations	
original parapet	
original roof form & finish original	
chimneys	The state of the s
INTEGRITY RATING excellent good	d fair poor
ALTERATIONS & SPECIFIC GUIDELINES	
No. Sympathetic S.G. Inapprop	priate S.G. Extremely Inappropriate S.G.
VER. POSTS	
BENCE	
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method COMMENTS	

Г