## **BUILDING IDENTIFICATION FORM** RICHMOND CONSERVATION STUDY KENT **BUILDING ADDRESS** TYPE **BUILDING TITLE** If not residence **EXISTING DESIGNATION** HBR NER NTC **GRADING** C D E CONSERVATION AREA [ STREETSCAPE 1 2 3 25 SURVEY DATE 11-9.84 NEG. FILE **PERIOD** Edwardian Early Victorian Victorian Late Victorian **CONSTRUCTION DATE** Source MATERIALS Walls TIMBER ASHLAR ROOF IRON **FORM** Detached Attached SIGNIFICANT FEATURES early paint gable decoration original unpainted intact verandah decoration wall finish early ornamental wall detailing fence original early garden doors/windows other prominent intact verandah structure contrib, elevations original TIMBER parapet VER, FLR. original roof original chimneys INTEGRITY RATING fair \_\_\_\_ excellent good poor **ALTERATIONS & SPECIFIC GUIDELINES** No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G. KENCE DOOR VER. FASCIA PANEL S = reinstate sympathetic alternative R = remove RAM = Remove by approved method O = reinstate original designs COMMENTS