BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY
BUILDING ADDRESS 175 KENT ST
BUILDING TITLE TYPE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 1-10-64 NEG. FILE 14-10  PERIOD  Early Victorian
INTEGRITY RATING excellent good fair poor ALTERATIONS & SPECIFIC GUIDELINES
No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G.
FENCE
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method
COMMENTS Timber achler terrace residence of high integrity. Few dauble storey timber dwellings survive in Elichmand.