BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS 90, 92 LENNOX ST.

BUILDING TITLE

TYPE If not residence

EXISTING DESIGNATION HBR ☐ NER ☐ NTC ☐

GRADING A ☐ B ☐ C ☐ D ☒ E ☐ F ☐

STREETSCAPE 1 ☐ 2 ☐ 3 ☐ **CONSERVATION AREA** ☐

SURVEY DATE 2.8.84 **NEG. FILE** 55 – 24

PERIOD

Early Victorian ☐ Edwardian ☐

Victorian ☐

Late Victorian ☒

CONSTRUCTION DATE Source

MATERIALS

Walls BRICK Roof IRON

FORM

Attached ☐ SEMI Detached ☒

SIGNIFICANT FEATURES

early paint colour scheme	☐	eaves, roof or gable decoration	☒
original unpainted wall finish	☐	intact verandah decoration 90	☒
ornamental wall detailing	☐	early fence	☐
original doors/windows 90	☒	early garden	☐
intact verandah structure 90	☒	other prominent contrib. elevations	☒ 90
original parapet	☐		☐
original roof form & finish	☒		☐
original chimneys 90	☒		☐



INTEGRITY RATING excellent ☐ good ☒ 90 fair ☐ poor ☒ 92

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
92			PERGOLA	R	ALUMIN. WINDOW	90
	FENCES		PAINTED BRICKWK	RAM		

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS