

BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS 128 LENNOX ST

BUILDING TITLE BERMONDSEY

TYPE
If not residence

EXISTING DESIGNATION HBR ☐ NER ☐ NTC ☐

GRADING A ☐ B ☐ C ☒ D ☐ E ☐ F ☐

STREETSCAPE 1 ☐ 2 ☐ 3 ☒ CONSERVATION AREA ☒

SURVEY DATE 11.7.84 NEG. FILE 33-13

PERIOD

Early Victorian ☐ Edwardian ☒
Victorian ☐
Late Victorian ☐

CONSTRUCTION DATE 1903 Source PARAPET

MATERIALS


Walls BRICK Roof IRON

FORM

Attached ☐ Semi-Detached ☒

SIGNIFICANT FEATURES

early paint colour scheme <input type="checkbox"/>	eaves, roof or gable decoration <input type="checkbox"/>
original unpainted wall finish <input type="checkbox"/>	intact verandah decoration <input checked="" type="checkbox"/>
ornamental wall detailing <input type="checkbox"/>	early fence <input type="checkbox"/>
original / early doors/windows <input checked="" type="checkbox"/>	early garden <input type="checkbox"/>
intact verandah structure <input checked="" type="checkbox"/>	other prominent contrib. elevations <input checked="" type="checkbox"/>
original parapet <input checked="" type="checkbox"/>	Early shopfront <input checked="" type="checkbox"/>
original roof form & finish <input checked="" type="checkbox"/>	<input type="checkbox"/>
original chimneys <input checked="" type="checkbox"/>	<input type="checkbox"/>



INTEGRITY RATING excellent ☐ good ☐ fair ☒ poor ☐

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
					PAINTED BRICKWORK	RAM
					AIR CONDITIONER	S

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS

Arched Victorian building retaining an early shopfront, and intact parapet detail.