BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY	
BUILDING ADDRESS 138 VENNOX	41. and Bower St
BUILDING TITLE	TYPE If not residence
EXISTING DESIGNATION HBR	NER NTC
GRADING A B C D E F	
STREETSCAPE 1 2 3	CONSERVATION AREA
PERIOD  Early Victorian	
INTEGRITY RATING excellent good fair poor ALTERATIONS & SPECIFIC GUIDELINES	
No. Sympathetic S.G. Inappro	priate S.G. Extremely Inappropriate S.G.
FENCE	9
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method  COMMENTS  Norther this building nor Bowen St. indicated on bounds Pept 1855 May  of Richmand (by Kearney)  Rominantly positioned victorian residence with projecting lay window and articular	

hna verandal