

# BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS 140, 142 LENNOX ST

BUILDING TITLE \_\_\_\_\_ TYPE  If not residence

EXISTING DESIGNATION HBR  NER  NTC

GRADING A  B  C  D  E  F

STREETSCAPE 1  2  3  CONSERVATION AREA

SURVEY DATE 11.7.84 NEG. FILE 33-16

**PERIOD**

Early Victorian  Edwardian   
 Victorian  Inter War   
 Late Victorian

CONSTRUCTION DATE \_\_\_\_\_ Source \_\_\_\_\_

**MATERIALS**


Walls CEMENT RENDER Roof IRON

**FORM**

Attached  Semi Detached

**SIGNIFICANT FEATURES**

early paint colour scheme <input type="checkbox"/>	eaves, roof or gable decoration <input type="checkbox"/>
original unpainted wall finish <input type="checkbox"/>	intact verandah decoration <input type="checkbox"/>
ornamental wall detailing <input type="checkbox"/>	early fence <input type="checkbox"/>
original <u>early</u> doors/windows <input checked="" type="checkbox"/>	early garden <input type="checkbox"/>
intact verandah structure <input type="checkbox"/>	other prominent contrib. elevations <input type="checkbox"/>
original parapet <input type="checkbox"/>	
original roof form & finish <input type="checkbox"/>	
original chimneys <input type="checkbox"/>	



INTEGRITY RATING excellent  good  fair  poor

**ALTERATIONS & SPECIFIC GUIDELINES**

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
<u>140</u>					<u>FENCE</u>	<u>S</u>
<u>140, 142</u>					<u>VERANDAH</u>	<u>S</u>

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

**COMMENTS**