BUILDING IDENTIFICATION FORM
BUILDING ADDRESS 172 Lennox Giveet
BUILDING TITLE TYPE
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 21/11/04 NEG. FILE , 11/0 - 3/15   PERIOD   Early Victorian   Victorian   Late Victorian     CONSTRUCTION DATE   Source
MATERIALS
Walls Brok Roof Terr. Tiley
FORM Gemi- Attached Detached
SIGNIFICANT FEATURES         early paint colour scheme       eaves, roof or gable decoration         original unpainted wall finish       intact verandah decoration         ornamental wall detailing       early fence         original doors/windows       early garden         intact verandah structure       other prominent contrib. elevations         original parapet       other prominent contrib. elevations         original parapet       intact verandah contrib. elevations
INTEGRITY RATING excellent good fair poor
ALTERATIONS & SPECIFIC GUIDELINES         No.       Sympathetic       S.G.       Inappropriate       S.G.       Extremely Inappropriate       S.G.         No.       Sympathetic       S.G.       Inappropriate       S.G.       Extremely Inappropriate       S.G.         No.       Sympathetic       S.G.       Inappropriate       S.G.       Fence       G         No.       Sympathetic       S.G.       S.G.       Fence       G       G         No.       Sympathetic       S.G.       S.G.       Fence       G       G         No.       Sympathetic       S.G.       S.G.       S.G.       Fence       G       G         No.       S.G.       S.G.       S.G.       S.G.       Fence       G       G         Sympathetic       S.G.       S.G.       S.G.       S.G.       S.G.       G       G         Sympathetic
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method