BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY
BUILDING ADDRESS 203 LENNOX ST
BUILDING TITLE TYPE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 25.7.64 NEG. FILE 18-27 PERIOD Early Victorian Edwardian Victorian Source MATERIALS Walls BRICK Roof T.C. TILE FORM Attached Detached SIGNIFICANT FEATURES early paint colour scheme original unpainted wall finish decoration ornamental wall detailing fence original doors/windows intact verandah structure contrib. elevations original parapet Proper in the parapet original parapet original parapet Proper in the parapet original parapet origi
original chimneys
INTEGRITY RATING excellent good fair poor ALTERATIONS & SPECIFIC GUIDELINES
No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G.
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method COMMENTS Altractive tamboar viewandah defailing is a feature of this tedwardian vandance.