

# CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

LORRAINE HUDDLE **211382**  
 LOUISE HONMAN  
 RICHARD AITKEN  
 1986

BUILDING ADDRESS **4 Weller St** Type **Res** Original Use **Res**

PRESENT BUILDING TITLE

EXISTING DESIGNATION & FILE No. HBR No.  NER No.  NTC FN.  GRC No.

GRADING A  B  C  D  E  S

STREETSCAPE LEVEL 1  2  3  CONSERVATION AREA

SURVEY DATE **21-3-86**

NEG. FILE **011-003** <sup>003</sup> **011-003** ? **not 011-003**

PERIOD

Early Victorian

Victorian

Late Victorian

Edwardian

Inter War

Post War

MATERIALS

walls **wh'nd** roof **c-iron**

CONSTRUCTION DATE source

SIGNIFICANT FEATURES

original materials <input checked="" type="checkbox"/>	early paint colour scheme or original unpainted finish <input type="checkbox"/>	ornamental wall detailing <input type="checkbox"/>
original doors, windows, hoods <input checked="" type="checkbox"/>	intact verandah / porch structure <input checked="" type="checkbox"/>	original parapet <input type="checkbox"/>
original roof form and finish <input checked="" type="checkbox"/>	original chimneys <input type="checkbox"/>	eaves roof or gable decoration <input checked="" type="checkbox"/>
intact verandah decoration <input checked="" type="checkbox"/>	early fence <input type="checkbox"/>	early garden <input type="checkbox"/>
other prominent contributing elevations <input type="checkbox"/>		

INTEGRITY RATING excellent  good  fair  poor

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	
			<b>fence</b>	<b>S</b>	<b>con. ver floor</b>	<b>S</b>
					<b>garden</b>	<b>S</b>
					<b>gates</b>	<b>S</b>

o : reinstate original design r : remove  
 s : reinstate sympathetic alternative ram : remove by approved method