CITY OF GEELONG WEST

URBAN CONSERVATION STUDY: BUILDING IDENTIFICATION FORM.

LORRAINE HUDDLE 21386
LOUISE HONMAN
RICHARD AITKEN
1986

BUILDING ADDRESS 9 Weller St

Type Res

Original Use Res

PRESENT BUILDING TITLE "Lildonan"

EXISTING DESIGNATION & FILE No. HBR No. [ ] NER No. [ ] NTC FN. [ ] GRC No. [ ]

GRADING A [ ] B [ ] C [/] D [ ] E [ ] S [ ]

STREETSCAPE LEVEL 1 [ ] 2 [/] 3 [ ] CONSERVATION AREA [ ]

SURVEY DATE 21-3-86

NEG. FILE 010-~~037~~ 036

PERIOD

- Early Victorian [ ]
- Victorian [/]
- Late Victorian [ ]
- Edwardian [ ]
- Inter War [ ]
- Post War [ ]

MATERIALS

walls tim roof ci

CONSTRUCTION DATE c 1870s source

SIGNIFICANT FEATURES

original materials	[/]	early paint colour scheme or original unpainted finish	[ ]	ornamental wall detailing	[ ]
original ~~doors~~, windows, hoods	[/]	intact verandah / porch structure	[/]	original parapet	[ ]
original roof form and finish	[/]	original chimneys	[/]	eaves roof or gable decoration	[ ]
intact verandah decoration	[/]	early fence	[ ]	early garden	[ ]
other prominent contributing elevations	[ ]		[ ]		[ ]

INTEGRITY RATING excellent [ ] good [/] fair [ ] poor [ ]

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	
			fence	s	brick balustrade	r.

o : reinstate original design r : remove
s : reinstate sympathetic alternative ram: remove by approved method