

# BUILDING IDENTIFICATION FORM

## RICHMOND CONSERVATION STUDY

**BUILDING ADDRESS** *10, 12 LOYOLA GROVE*

**BUILDING TITLE** \_\_\_\_\_ **TYPE**  
If not residence \_\_\_\_\_

**EXISTING DESIGNATION** HBR       **NER**       **NTC**

**GRADING**      A       B       C       D       E       F

**STREETSCAPE**      1       2       3       **CONSERVATION AREA**

**SURVEY DATE** *11.9.04*      **NEG. FILE** *79 - 6*

**PERIOD**

Early Victorian       Edwardian

Victorian       \_\_\_\_\_

Late Victorian

**CONSTRUCTION DATE** \_\_\_\_\_ **Source** \_\_\_\_\_

**MATERIALS**

Walls *BRICK*      Roof *T.C. TILE*

**FORM**

Attached       Detached

**SIGNIFICANT FEATURES**

|                                |   |                                     |   |
|--------------------------------|---|-------------------------------------|---|
| early paint colour scheme      | <input type="checkbox"/>                      | eaves, roof or gable decoration     | <input type="checkbox"/>                      |
| original unpainted wall finish | <input type="checkbox"/>                      | intact verandah decoration          | <i>10</i> <input checked="" type="checkbox"/> |
| ornamental wall detailing      | <input type="checkbox"/>                      | early fence                         | <input type="checkbox"/>                      |
| original doors/windows         | <input checked="" type="checkbox"/>           | early garden                        | <input type="checkbox"/>                      |
| intact verandah structure      | <i>10</i> <input checked="" type="checkbox"/> | other prominent contrib. elevations | <input type="checkbox"/>                      |
| original parapet               | <input type="checkbox"/>                      |                                     | <input type="checkbox"/>                      |
| original roof form & finish    | <input checked="" type="checkbox"/>           |                                     | <input type="checkbox"/>                      |
| original chimneys              | <input checked="" type="checkbox"/>           |                                     | <input type="checkbox"/>                      |



**INTEGRITY RATING**      excellent       good  *10*      fair  *12*      poor

**ALTERATIONS & SPECIFIC GUIDELINES**

| No. | Sympathetic | S.G. | Inappropriate            | S.G.       | Extremely Inappropriate | S.G.     |
|-----|-------------|------|--------------------------|------------|-------------------------|----------|
|     |             |      | <i>PAINTED BRICKWORK</i> | <i>RAM</i> | <i>FENCES</i>           | <i>S</i> |
|     |             |      |                          |            |                         |          |
|     |             |      |                          |            |                         |          |
|     |             |      |                          |            |                         |          |
|     |             |      |                          |            |                         |          |

O = reinstate original designs      S = reinstate sympathetic alternative      R = remove      RAM = Remove by approved method

**COMMENTS**