BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY
BUILDING ADDRESS 78 LYNDHURST ST.
BUILDING TITLE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 18.7.84 NEG. FILE 50 - 3
PERIOD Early Victorian Edwardian Victorian Late Victorian Source
MATERIALS Walls WEATHER B'D. Roof IRON
FORM Attached Detached SIGNIFICANT FEATURES
early paint colour scheme gable decoration gable decoration intact verandah decoration ornamental wall finish garden original dears/windows intact verandah structure original parapet original chimneys chimneys carbon colours or gable decoration carbon colour garden other prominent contrib. elevations carbon colour c
INTEGRITY RATING excellent good fair poor
ALTERATIONS & SPECIFIC GUIDELINES No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G. ARCHITRAMES S PAGE PAGE ARCHITRAMES S ARCHITRAM
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method
Building shown in this location on Lands Depot 1855 Map of Kichmond