BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY
BUILDING ADDRESS 2 MANESON ST
BUILDING TITLE TYPE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 5.7.84 NEG. FILE 38-4
PERIOD  Early Victorian
chimneys
INTEGRITY RATING excellent good fair poor
ALTERATIONS & SPECIFIC GUIDELINES  No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G.
FENCE
O = reinstate original designs  S = reinstate sympathetic alternative  R = remove  RAM = Remove by approved method
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method  COMMENTS  This well introducted to wavdid a conver residence, features a high standard of detail and vidge weeting, bracketed window had, and garden uns