

BUILDING IDENTIFICATION FORM

RICHMOND CONSERVATION STUDY

BUILDING ADDRESS *3 MALLESON ST.*

BUILDING TITLE *CLONMORE*

TYPE
If not residence

EXISTING DESIGNATION HBR NER NTC

GRADING A B C D E F

STREETSCAPE 1 2 3 CONSERVATION AREA

SURVEY DATE *23.7.84* NEG. FILE *52-25*

PERIOD

Early Victorian Edwardian
Victorian
Late Victorian

CONSTRUCTION DATE Source

MATERIALS


Walls *BRICK* Roof *T.C. TILE*

FORM

Attached Detached

SIGNIFICANT FEATURES

early paint colour scheme <input type="checkbox"/>	eaves, roof or gable decoration <input checked="" type="checkbox"/>
original unpainted wall finish <input checked="" type="checkbox"/>	intact verandah decoration <input checked="" type="checkbox"/>
ornamental wall detailing <input type="checkbox"/>	early fence <input type="checkbox"/>
original doors/windows <input checked="" type="checkbox"/>	early garden <input type="checkbox"/>
intact verandah structure <input checked="" type="checkbox"/>	other prominent contrib. elevations <input type="checkbox"/>
original parapet <input type="checkbox"/>	<i>STEPS,</i> <input checked="" type="checkbox"/>
original roof form & finish <input checked="" type="checkbox"/>	<i>VER. 31</i> <input type="checkbox"/>
original chimneys <input checked="" type="checkbox"/>	<i>PATH TILES</i> <input type="checkbox"/>
	<i>SCREEN DOOR</i> <input checked="" type="checkbox"/>



INTEGRITY RATING excellent good fair poor

ALTERATIONS & SPECIFIC GUIDELINES

No.	Sympathetic	S.G.	Inappropriate	S.G.	Extremely Inappropriate	S.G.
			<i>FENCE</i>	<i>S</i>		
			<i>MARBLETTED WALLS</i>	<i>R</i>		

O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method

COMMENTS

Competently detailed brick late Edwardian villa of generally good integrity with notable screen door