BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY
BUILDING ADDRESS 9 MALLESON ST.
BUILDING TITLE TYPE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 23. 7.84 NEG. FILE 52 - 23
PERIOD Early Victorian Victorian Late Victorian
CONSTRUCTION DATE Source
MATERIALS Walls WEATHERS'D. Roof IRON
FORM Attached Detached
SIGNIFICANT FEATURES early paint colour scheme gable decoration gable gable decoration gable decoration gable decoration gable gabl
INTEGRITY RATING excellent good fair poor
ALTERATIONS & SPECIFIC GUIDELINES No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G. FINAL S.G. Sympathetic S.G. Extremely Inappropriate S.G.
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method
COMMENTS