BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY
BUILDING ADDRESS 16, 18 MALLESON ST
BUILDING TITLE TYPE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 5.7.84 NEG. FILE 34-37
PERIOD Early Victorian Edwardian Victorian Late Victorian Capacita Capaci
CONSTRUCTION DATE Source
MATERIALS TIMBER ASHLAR & Walls WEATHERBOARD Roof IRON
FORM Attached Detached Detached
SIGNIFICANT FEATURES early paint colour scheme gable decoration gramental wall detailing garden g
INTEGRITY RATING excellent good fair poor ALTERATIONS & SPECIFIC GUIDELINES
No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G.
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method
COMMENTS