BUILDING IDENTIFICATION FORM RICHMOND CONSERVATION STUDY
BUILDING ADDRESS 76 MAKY 47
BUILDING TITLE TYPE If not residence
EXISTING DESIGNATION HBR NER NTC
GRADING A B C D E F
STREETSCAPE 1 2 3 CONSERVATION AREA
SURVEY DATE 18.7.84 NEG. FILE 31-19 PERIOD Early Victorian Edwardian Victorian Late Victorian CONSTRUCTION DATE MATERIALS Walls WEATHER BOKKET Roof RON
FORM Attached Detached SIGNIFICANT FEATURES early paint colour scheme gable decoration gable decoration original unpainted wall finish decoration ornamental wall detailing original doors/windows garden original parapet original parapet original parapet original chimneys original chimneys
INTEGRITY RATING excellent good fair poor
ALTERATIONS & SPECIFIC GUIDELINES No. Sympathetic S.G. Inappropriate S.G. Extremely Inappropriate S.G. VERMOVED VERMOVED VERMOVED VERMOVED VERMOVED PARTICIPATION PROPRIEM NOT A PROPRIEM TO A
O = reinstate original designs S = reinstate sympathetic alternative R = remove RAM = Remove by approved method COMMENTS